

stavebniny



Enter Setup



Restore Default Settings

Scanner Settings



Scanning Timeout



0x00



Validate



Auto Power Off



0x00



Validate



Power Saving Duration



0x00



Validate

Interface Settings : USB HID via 3656



HID PCAT (US)



0x06



0x04



Validate



QWERTZ



Numeric Key Pad



Update